Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

H65 ALMAX AUTO REPAIR INC. NY AST A100293003
West 2757 STILLWELL AVENUE N/A

1/8-1/4 0.152 mi.

800 ft. Site 1 of 3 in cluster H

BROOKLYN, NY 11224

Relative: AST: Higher Name:

HigherName:ALMAX AUTO REPAIR INC.Actual:Address:2757 STILLWELL AVENUE1 ft.City,State,Zip:BROOKLYN, NY 11224

 Region:
 STATE

 DEC Region:
 2

 Site Status:
 Active

 Facility Id:
 2-609783

 Program Type:
 PBS

UTM X: 586161.74730
UTM Y: 4492663.20354
Expiration Date: 12/03/2019
Site Type: Other

Affiliation Records:

Site Id: 334661

Affiliation Type: Facility Owner

Company Name: LEONID LOTOVSKY

Contact Type: PRESIDENT

Contact Name: LEONID LOTOVSKY

Address1: 2757 STILLWELL AVENUE

 Address2:
 Not reported

 City:
 BROOKLYN

 State:
 NY

 Zip Code:
 11224

 Country Code:
 001

Phone: (718) 449-6554
EMail: Not reported
Fax Number: Not reported
Modified By: LSZINOMA
Date Last Modified: 2014-12-08

Site Id: 334661 Affiliation Type: Mail Contact

Company Name: ALMAX AUTO REPAIR INC.

Contact Type: PRESIDENT
Contact Name: LEONID LOTOVSKY
Address1: 2757 STILLWELL AVENUE

Address2: Not reported City: BROOKLYN State: NY Zip Code: 11224 Country Code: 001

Phone: (718) 449-6554

EMail: ALMAXAUTO@GMAIL.COM

Fax Number: Not reported Modified By: LSZINOMA Date Last Modified: 2014-12-08

Site Id: 334661

Affiliation Type: Facility Operator

Company Name: ALMAX AUTO REPAIR INC.

Contact Type: Not reported
Contact Name: LEONID LOTOVSKY

Map ID MAP FINDINGS

Direction Distance

EDR ID Number Elevation Database(s) EPA ID Number Site

> Address1: Not reported Address2: Not reported City: Not reported State: NN

> Zip Code: Not reported Country Code: 001

Phone: (718) 449-6554 Not reported EMail: Fax Number: Not reported Modified By: **NRLOMBAR** Date Last Modified: 2004-12-03

334661 Site Id:

Affiliation Type: **Emergency Contact**

Company Name: ALMAX AUTO REPAIR INC.

Contact Type: Not reported

Contact Name: LEONID LOTOVSKY

Address1: Not reported Not reported Address2: City: Not reported State: NN Zip Code: Not reported

Country Code: 001

Phone: (718) 449-6554 EMail: Not reported Fax Number: Not reported Modified By: NRLOMBAR Date Last Modified: 2004-12-03

Tank Info:

Tank Number: 001 181022 Tank Id: Material Code: 0022

Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

E00 - Piping Secondary Containment - None A00 - Tank Internal Protection - None

G10 - Tank Secondary Containment - Impervious Underlayment

K00 - Spill Prevention - None B00 - Tank External Protection - None C00 - Pipe Location - No Piping

F00 - Pipe External Protection - None 104 - Overfill - Product Level Gauge (A/G)

J00 - Dispenser - None D00 - Pipe Type - No Piping

H06 - Tank Leak Detection - Impervious Barrier/Concrete Pad (A/G)

L00 - Piping Leak Detection - None

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated

above grade or tank pad, allowing visual inspection.

Tank Type: Steel/Carbon Steel/Iron

Tank Status: In Service Pipe Model: Not reported Install Date: 10/01/1988 Capacity Gallons: 275 Tightness Test Method: NN

Date Test: Not reported

Map ID
Direction
Distance
Elevation

Site

MAP FINDINGS

EDR ID Number Database(s) EPA ID Number

Next Test Date: Not reported
Date Tank Closed: Not reported
Register: True
Modified By: LSZINOMA
Last Modified: 04/14/2017
Material Name: waste oil/used oil